HO-1086

8507 Guilford Road Private

#### Description:

The house at 8507 Guilford Road faces south toward the road and is a one-story frame rancher with a "T" plan. It is banked into a hill on the south, with an exposed basement on the north. It has a gable on hip roof at the west end with asphalt shingles and an east-west ridge, and a cross gable on the eastern end, where the crossbar of the "T" is, that has a north-south ridge. There is a parged foundation and aluminum siding. The south elevation is six bays, with roll-up garage doors in the two western bays, and an interior ashlar stone chimney between these two bays and the two center bays. The west-center bay has a rounded bay window with five eight-light sash, and the east-center bay has a door with two bolection-moulded panels. The eastern two bays each have paired six-over-six sash. There is a pent roof above these two bays, with the gable end above this pent roof. The north elevation has a brick retaining wall between the center and western bays, with the western bays below grade, and a deck across the eastern and center bays of the first story.

### Significance:

The rancher at 8507 Guilford Road is designed with the private bedrooms located to one side of the front entrance, in the "T", and the public rooms to the other side (in this case, the west). The garage, which is now an integral part of the house, is connected to these western, public rooms. The focal point of the front façade is the bay window in the center of the house, and this is the most public room, the living room. The focal point of this room is the fireplace, which remains a traditional element in an otherwise modern reinterpretation of the American dwelling. The long, low character of the rancher is clearly influenced by the Prairie style architecture of the early twentieth century, though the dwelling type did not really become common until the 1950s; at the same time it is straddling the line between traditional and modern, since it still relies greatly on traditional building materials. This example is dated 1961 according to the tax assessment records, and there is no compelling reason to question the date.

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

	Property	(indicate preferred r			
historic					-
other					
2. Location					
street and number	r 8507 Guilford l	Road		_	not for publication
city, town	Columbia			<u>X</u>	vicinity
county	Howard		-		
3. Owner of	f Property	(give names and mailing	addresses of all owners)		
name	CMC Land LL	Ĉ	Transition of the second		
street and number	r 11710 Stonegat	e Lane		telephone	_
city, town	Columbia		state MD	zip code 2	1044
	In Fig. 1. Company of the Company of	Howard County Courthouse	30000000	9970 folio 73	
city, town	Ellicott City	tax map 42	tax parcel 250	tax ID n	umber
Dete	rmined Eligible for	n Local Historic District the National Register/Maryla or the National Register/Mary			
Histo	oric Structure Repo	rt or Research Report at MH	Т		

7.	Des	cri	otic	n
			~	

Inventory No. HO-1086

#### Condition

_	excellent	deteriorated
X	good	ruins
	fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The house at 8507 Guilford Road is located on the north side of the road just east of the intersection of Kindler Road, about 2 ½ miles south of Columbia and 1 ¾ miles southeast of Simpsonville in southern Howard County, Maryland. The house faces south toward the road and is a one-story frame rancher with a "T" plan. It is banked into a hill on the south, with an exposed basement on the north. It has a gable on hip roof at the west end with asphalt shingles and an east-west ridge, and a cross gable on the eastern end, where the crossbar of the "T" is, that has a north-south ridge. There is a parged foundation and aluminum siding.

The south elevation is six bays, with roll-up garage doors in the two western bays, and they have four panels above four lights, with eight lights at the bottom. There is an interior ashlar stone chimney between these two bays and the two center bays, and it is south of the ridge. The west-center bay has a rounded bay window with five eight-light sash, and there is a low ashlar stone wall below it. The east-center bay has a door with two bolection-moulded panels. The eastern two bays each have paired six-over-six sash. There is a pent roof above these two bays, carried around from the east and west sides of the gable roof, with the gable end above this pent roof.

The west elevation has no openings. The north elevation has two six-over-six sash in the eastern bays of the basement, three pairs of sliding glass doors in the center bays, and a brick retaining wall between the center and western bays, with the western bays below grade. The first story has a deck across the eastern and center bays. The eastern bay has paired six-over-six sash and the east-east-center bay has a single six-over-six sash. The east-center bay has a sliding glass door, the west-center bay has paired small six-over-six sash, and the western section has a single west bay with a door that has nine lights over a cross buck.

The east elevation has two six-over-six sash on both the basement and first story.

8. Signific	ance			Inventory No. HO-1086
Period	Areas of Significance	Check and j	ustify below	
1600-1699 1700-1799 1800-1899 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government =_ religion science social history transportation other:
Specific dates	N/A	· ·	Architect/Builder N/A	
Construction da	ates c. 1961			
Evaluation for:				
	National Register		Maryland Register	Xnot evaluated
(	National Register		Maryland Register	Xnot evaluated

8 Significance

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form - see manual.)

The rancher at 8507 Guilford Road is designed with the private bedrooms located to one side of the front entrance, in the "T", and the public rooms to the other side (in this case, the west). The garage, which is now an integral part of the house, is connected to these western, public rooms. The focal point of the front facade is the bay window in the center of the house, and this is the most public room, the living room. The focal point of this room is the fireplace, which remains a traditional element in an otherwise modern reinterpretation of the American dwelling. The long, low character of the rancher is clearly influenced by the Prairie style architecture of the early twentieth century, though the dwelling type did not really become common until the 1950s; at the same time it is straddling the line between traditional and modern, since it still relies greatly on traditional building materials. This example is dated 1961 according to the tax assessment records, and there is no compelling reason to question the date. This house was scheduled to be demolished in early 2012 for redevelopment of the site.

# 9. Major Bibliographical References

Inventory No. HO-1086

# 10. Geographical Data

Acreage of surveyed property 1.007 A Acreage of historical setting 1.007 A Quadrangle name Savage

Quadrangle scale: 1:24000

#### Verbal boundary description and justification

The boundaries consist of the outlines of the property, tax map 42, parcel 250, which encompasses all of the historic buildings and features on the site.

## 11. Form Prepared by


name/title	Ken Short	100	
organization	Howard County Department of Planning & Zoning	date	May 2012
street & number	3430 Courthouse Drive	telephone	410-313-4335
city or town	Ellicott City	state	MD

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



HO-1086

8507 Guilford Road Savage quad

8507 Guilford Road Howard County, Maryland Ken Short, photographer

Photo Log
Nikon D-70 camera
HP Premium Plus paper
HP Gray Photo print cartridge

HO-1086\_2012-02-27\_01 South elevation

HO-1086\_2012-02-27\_02 North elevation



41111 40-1086 2507 Guilford Road Howard County, Maryland Ken Short 2012-02-27 MD SHPO South Elevation 1042





-

HO-1086

8507 Guilford Road Howard County, Maryland Ken Short 2012-02-27 MD SHPO Northelevation 20f2

